

Summary

TEL: (+973) 17321181/2  
FAX: (+973) 17323876  
AFTN: OB BBYNYX  
SDC@caa.gov.bh  
www.caa.gov.bh/ais

KINGDOM OF BAHRAIN  
MINISTRY OF TRANSPORTATION  
CIVIL AVIATION AFFAIRS  
AERONAUTICAL INFORMATION  
MANAGEMENT  
P.O.BOX 586



SUMMARY  
TYPE : NOF  
FORMAT : BULLETIN

QUERY: (ADHOC)  
SYSTEM TIME: 17-07-02 04:56

- S U M M A R Y -

**BAHRAIN**

BEFORE: 17-07-02 04:42

NOF LIST : OB BB 1A

**NOTAM OFFICE INFORMATION**

OB BB - BAHRAIN

NOTAM  
AGA

OB BB A0218/17 REPLACED BY OB BB A0243/17

FROM: 17-06-29 20:55 TO: PERM  
OB BI - BAHRAIN INTL  
E) FUEL AVGAS 100 LL AVAILABLE AT BIA LIMITED TO 37 USG. AND MORE  
QUANTITY AVAILABLE BY PRIOR ARRANGEMENT WITH BAFCO (BAHRAIN AVIATION  
FUELLING COMPANY) TEL:+973 17329440 EFAX:+973 17910925  
AMEND OB BB AIP FIR PAGES AD 2.4 ACCORDINGLY

OB BB A0094/17 REPLACED BY OB BB A0217/17

FROM: 17-06-12 11:04 TO: 17-09-12 23:59 EST  
OB BB - BAHRAIN  
E) OPERATORS ARE REMINDED OF THE REQUIREMENT TO FILE FLIGHT PLANNED  
ROUTES IN ACCORDANCE WITH BAHRAIN AIP SUP 06/17.  
THIS DOCUMENT CONTAINS NOTES THAT MUST BE READ IN ADDITION TO THE  
ROUTES SPECIFIED.  
AIR SAFETY REPORTING PROCEDURES WILL BE CARRIED OUT ON ALL  
INCORRECTLY FILED ROUTES IN THE OB BB FIR AND PILOTS WILL BE ADVISED  
WHEN THIS IS DONE.

OB BB A0216/17

FROM: 17-06-16 03:00 TO: 17-07-08 13:00  
OB BS - BAHRAIN/ISA AIRBASE  
D) 16,17,23 AND 24 JUNE 2017 BTN 0300 - 1100  
30 JUNE, 01, 07 AND 08 JULY 2017 BTN 0300 - 1300  
E) DUE TO WIP AT FIRST 400M RWY 15L. TFC DEPARTING RWY 15L TO DEPART  
VIA TWYL T2 WITH REMAINING DISTANCE 3000M. TFC LANDING RWY 33R TO  
VACATE THE RWY VIA TWYL T2 OR EARLIER.

OB BB A0178/17

Summary

FROM: 17-05-15 09:40 TO: 17-08-15 23:59 EST  
OBBI - BAHRAIN INTL  
D) H24  
E) ACFT STAND A28 CLOSED DUE TO WIP

OBBB A0129/17

FROM: 17-04-15 00:01 TO: PERM  
OBBS - BAHRAIN/ISA AIRBASE  
E) MAIN RWY 15L/33R WILL BE AVAILABLE TO BE USED AGAIN.  
AND RWY 15R/33L WILL BE USED AS BACKUP OR EMERGENCY RWY FOR CODE C  
OR SMALLER AIRCRAFTS ONLY.  
AMEND BAHRAIN AIP PAGES ACCORDINGLY

OBBB A0128/17

FROM: 17-04-15 00:01 TO: PERM  
OBBS - BAHRAIN/ISA AIRBASE  
E) AMEND RWY 15/33 FOR ISA AIRBASE AERODROME TO READ AS 15L/33R.  
AMEND BAHRAIN AIP PAGES ACCORDINGLY

OBBB A0008/16

FROM: 17-10-10 00:30 TO: 17-10-21 03:15  
OBBI - BAHRAIN INTL  
D) DLY BTN 0030-0315  
E) RWY30R/12L CLOSED DUE TO WIP

OBBB A0007/16

FROM: 17-07-06 09:25 TO: 17-07-06 11:25  
OBBI - BAHRAIN INTL  
E) RWY 30R/12L CLOSED DUE WIP

INFO

OBBB A0203/17 REPLACED BY OBBB A0245/17

FROM: 17-07-01 06:36 TO: 17-08-01 23:59 EST  
OBBB - BAHRAIN  
E) CHECKLIST

2016: 0007 0008  
2017: 0089 0128 0129 0167 0170 0178 0204 0213 0216 0217 0219 0220  
0222 0235 0236 0237 0238 0239 0240 0241 0243

LATEST AIP AMENDMENT : AIRAC 06/17 DATED 25 MAY 2017  
NEXT AIP AMENDMENT : AIRAC 09/17 EFFECTIVE DATE 17 AUG 2017  
LATEST AIP SUPPLEMENT : SUP 06/17 DATED 25 MAY 2017  
LATEST AIC : 05/17 DATED 28 APR 2017

OBBB A0103/17 REPLACED BY OBBB A0241/17

FROM: 17-06-21 10:06 TO: 17-09-21 23:59 EST  
OBBI - BAHRAIN INTL  
E) OBSTACLE CRANE WILL BE ERECTED SOUTH OF RWY 12L/30R, SOUTH WEST OF TH  
E CONTROL TOWER. HEIGHT 45 METER, APPROX DEST 600M, MAG BRG  
222 DEG FROM THE ARP

OBBB A0215/17 REPLACED BY OBBB A0220/17

FROM: 17-06-13 11:54 TO: PERM  
OBBB - BAHRAIN

Summary

---

E) ALL ROUTES WITHIN BAHRAIN FIR ARE AVILABLE FOR FLIGHTS AFFECTED BY NO TAM A0219/17, EXCEPT THE FOLLOWING AWYS THAT FALL WITHIN BAHRAIN AIRSPACE:

- 1- B/UB457, L/UL604 AND N/UN685 BETWEEN DENVO AND NARMI
- 2- M/UM444 AND T/UT444 BETWEEN DENVO AND DESBU
- 3- N/UN318 BETWEEN LADNA AND ASTAD
- 4- A/UA453 BETWEEN ASTAD AND DESBU
- 5- P/UP699 BETWEEN ASTAD AND NARMI

OBBB A0212/17 REPLACED BY OBBB A0219/17

FROM: 17-06-13 11:54 TO: PERM

OBBB - BAHRAIN

E) ALL FLT REGISTERED IN THE STATE OF QATAR ARE NOT AUTHORISED TO OVERFLY BAHRAIN AIRSPACE.

OPERATORS NOT REGISTERED IN KINGDOM OF BAHRAIN INTENDING TO OPERATE NON-SCHEDULED FLIGHTS OR CHARTER INCLUDING PRIVATE FLIGHTS, CARGO AND PASSENGER FROM OR TO THE STATE OF QATAR VIA BAHRAIN AIRSPACE SHALL OBTAIN APPROVAL FROM BAHRAIN CAA BY PROVIDING A COPY OF THE DETAILED MANIFEST OF THE FLIGHT INCLUDING PASSENGER NAMES AT LEAST 24 HOURS PRIOR TO DEPARTURE TO THE FLW CONTACT:

TEL:00973 17329035 / 00973 17329096

EMAIL: SCHEDULE(AT)MTT.GOV.BH

OBBB A0087/17 REPLACED BY OBBB A0213/17

FROM: 17-06-08 11:01 TO: 17-09-08 23:59 EST

OBBB - BAHRAIN

D) DAILY BTN 0500-0700

E) ALL FLIGHTS DEPARTING OR OVERFLYING BAHRAIN FIR EXITING VIA ROTOX ON ATS ROUTE UT444 OR UT602 REQUESTED LEVELS FL340-FL360-FL380 MAY BE LIMITED TO LOWER LEVELS DUE TO TRAFFIC VOLUMES

OBBB A0204/17

FROM: 17-06-06 00:00 TO: PERM

OBBB - BAHRAIN

E) NO FLIGHT WILL BE ALLOWED FROM KINGDOM OF BAHRAIN TO STATE OF QATAR AND FROM STATE OF QATAR TO KINGDOM OF BAHRAIN.

OBBB A0056/17 REPLACED BY OBBB A0170/17

FROM: 17-05-11 07:45 TO: 17-08-20 23:59 EST

OBBB - BAHRAIN INTL

D) H24

E) OBST CRANE WILL BE ERECTED HEIGHT 45 M, POSITIONED AT APPROX DIST 540 M SOUTH OF RWY C/L SOUTH OF THE EASTERN APRON.

WORK WILL BE SUSPENDEED WHEN VISIBILITY LESS THAN 5000M

OBBB A0167/17

FROM: 17-05-03 11:43 TO: 17-08-03 23:59 EST

OBBB - BAHRAIN INTL

D) H24

E) OBST CRANE WILL BE ERECTED HEIGHT 28M, POSITIONED WEST OF THE RUNWAY AT APPROX DIST 500M, MAG BRG 277 DEG FROM RWY 12L THR.

OBBB A0089/17

FROM: 17-03-08 07:55 TO: PERM

OBBB - BAHRAIN

## Summary

---

E) MODE S AND SELECTED ALTITUDE USE IN THE OBBS FIR.  
PILOTS OF MODE S EQUIPPED AIRCRAFT, OPERATING IN THE OBBS FIR MUST  
ENSURE THAT THEIR CURRENT CLEARED LEVEL IS SET AS THE SELECTED  
ALTITUDE IN THE AIRCRAFT MODE CONTROL PANEL, UNLESS ESTABLISHED ON  
FINAL APPROACH FOR OBBI. EQUIPMENT FAILURE OR NONCOMPLIANT SHALL BE  
IMMEDIATELY REPORTED TO ATC

---END OF DOCUMENT---